KADUR DISTRICT.

Chickmagalur Sub-Division.

1. Yūpastambha at Hiremagaḷūr—Class II ; in good condition.
2. Vīranārāyaṇa Temple, Beḷavāḍi—Class I ; under the management of the Śringeri Jahgir ; the Deputy Commissioner states that it is a fine old structure badly neglected. The surroundings and the roof are overgrown with rank vegetation. The latter is said to be leaking badly. The chairman of the Panchayet is said to have promised to have the roof and the compound cleared of vegetation.
3. Mārkaṇḍēśvara Temple, Khāṇḍya—Class III ; not in good condition. Some repairs are said to have been effected by the P.W.D.
4. Siddēśvara Temple, Marle—Class II ; in good condition.
5. Chennakēśava Temple, Marle—Class II ; in good condition. Some repairs are being done.
6. Kaḷasēśvara Temple, Kaḷasa—In good condition. Annual repairs are being done from the temple funds.

Tarikere Sub-Division.

The undermentioned institutions are said to have been inspected during the year and are reported to be in good condition :—

1. Lakshmīkāntasvāmi Temple, Dēvanūr, Kadur Taluk.
2. Śiva Temple, Hirenallūr, Kaḍūr Taluk.
3. Amṛitēśvara Temple, Amritāpura, Tarikere Taluk.
4. Sōmēśvara Temple, Sompura, Tarikere Taluk.

MYSORE DISTRICT.

Mysore Sub-Division.

Jyōtirmayēśvara Temple, Śāligrāma—II Class. The Archak of the temple who is also the care-taker is reported to be not doing his work properly. It is learnt that an estimate for Rs. 4,500 had been prepared, but that the work was not taken up since the villagers did not come forward with their contribution. It is reported that the building is in a dilapidated condition and that rank vegetation has grown on the temple.

Rāmānujāchārya Temple, Śāligrāma—II Class. The monument is reported to be in good condition. But the care-taker is reported to be not doing his duty properly. In the Śrīpāḍa Tīrtha the flooring is said to be requiring cement-pointing.